



SANGATE AUTOMOTIVE & SERVICE CO.
 ABN: 16 006 673 827
 63 Henderson Road,
 Clayton Nth Victoria 3169
 Telephone: (03) 9562 5000
 Facsimile: (03) 9562 5888
 Email: sangateserviceco@motor.net.au

Pre-Purchase Inspection Report

(This report is subject to the conditions on the reverse of this form)

Report No.

K 19

Date

15/05/2009

Legend

A Attention required
 ✓ In order
 - Not applicable

31

Name
Shannons
 Address
 321 WARRIGAL ROAD
 CHELTENHAM
 VICTORIA, 3192

PHONE: 134646

Vehicle make and model

BENTLEY 8 TURBO

Body Style

SALOON

Year: 1988 Registration: WZB 076 Odometer: 4258 VIN: SCBZS0TA5JCH22818

Summary of overall condition of vehicle

GOOD FAIR POOR

Comments:

NEEDS ATTENTION TO RUST
 DRIVABILITY AND PERFORMANCE TEST GOOD

Engine/Exhaust

Engine Oil Condition Engine Noises Air Filter Fuel System Water Pump Exhaust Condition
 Oil Leaks Tune Condition Drive Belts Fuel Leaks Coolant Exhaust Mounts
 Engine Mounts Smoke Emission system Radiator/Hoses Thermostat Exhaust leaks

Comments:

ENGINE OIL LEAK

Transmission/Driveline

AUTOMATIC MANUAL

Transmission Shift Operation Noises Clutch OPS Linkages Drive shaft/ Boots
 Oil/Fluid Condition Mounts Inhibitor Switch Adjustment CV/Universal joints Final Drive

Comments:

Steering/Suspension

Power Assistance

YES NO

Steering Box/Rack Steering linkage Shock Absorbers Bushes/Pivots Tyre Wear Wheel/ Spare
 Oil Leaks Power Steering Springs Wheel Bearings Tyre Condition Driveability

Comments:

Brakes

Operation Pads/lining Pedal Height Wiring Indicators Battery
 Park brake Line Condition Pedal Rubbers Headlights/Aim Instrumentation Charge Rate
 Fluid leaks Hose Condition ABS check light Exterior Lighting Windscreen Wipers Horn

Comments:

Body

Structure Panel condition Previous Repairs Door/Window op Door Locks Seat Belts
 Corrosion Paint Condition Windscreen/glass Windows Tinting Seats and Trim Door handles

Comments:

REAR ELECTRICAL WINDOW SWITCHES INOPERATIVE
 VARIOUS PANEL AND PAINT DEFECTS. MINOR INTERIOR DEFECTS REAR ROOF LINING DEFECTIVE AND ADRIFT
 RUSTING AROUND SUN ROOF AREA CHASSIS SURFACE RUSTING
 RUSTING LOWER 1/4 PANEL, LOWER SILLS, WHEEL ARCHES AND FRONT LOWER GUARDS

Miscellaneous

Demister Air conditioner Heater LPG Compliance Ability to run on Alternative Fuels Other

Comments:

ELECTRIC EXTERIOR MIRRORS NOT ADJUSTING
 RUBBER ROD ON LEFT HAND REAR WHEEL ARCH MISSING
 REAR BUMPER BAR AND FRONT SPOILER NOT FITTING TRUE