



SANGATE AUTOMOTIVE & SERVICE CO.

ABN: 16 006 673 427
72 Henderson Road,
Clayton Nth Victoria 3169
Telephone: (03) 9562 5000
Facsimile: (03) 9562 5888
Email: sangateservice@bigpond.com

Pre-Purchase Inspection Report

(This report is subject to the conditions on the reverse of this form)

Report No.

T 22

Date

27/10/2016

Legend

- A Attention required
- ✓ In order
- Not applicable

16

Name
Shannons

Address
321 WARRIGAL ROAD PHONE: 134646
CHELTENHAM
VICTORIA, 3192

Vehicle make and model

ROLLS ROYCE SILVER CLOUD

Body Style

SALOON

Year

1961

Registration

Odometer

98570

VIN

SXC559

Summary of overall condition of vehicle

GOOD

FAIR

POOR

Comments:

V8 TWIN CARBY / AUTO TRANSMISSION

CLEAN AND TIDY VEHICLE

DRIVABILITY AND PERFORMANCE TEST GOOD

Engine/Exhaust

- | | | | | | |
|------------------------|------------------|-------------------|------------------|--------------|---------------------|
| ✓ Engine Oil Condition | ✓ Engine Noises | ✓ Air Filter | ✓ Fuel System | ✓ Water Pump | ✓ Exhaust Condition |
| ✓ Oil Leaks | ✓ Tune Condition | ✓ Drive Belts | ✓ Fuel Leaks | ✓ Coolant | ✓ Exhaust Mounts |
| ✓ Engine Mounts | - Smoke | - Emission system | ✓ Radiator/Hoses | ✓ Thermostat | ✓ Exhaust leaks |

Comments:

Transmission/Driveline

AUTOMATIC

MANUAL

- | | | | | | |
|-----------------------|-------------------|--------------------|--------------|-----------------------|----------------------|
| ✓ Transmission | ✓ Shift Operation | ✓ Noises | - Clutch OPS | ✓ Linkages | ✓ Drive shaft/ Boots |
| ✓ Oil/Fluid Condition | ✓ Mounts | - Inhibitor Switch | ✓ Adjustment | ✓ CV/Universal joints | ✓ Final Drive |

Comments:

Steering/Suspension

Power Assistance

YES

NO

- | | | | | | |
|---------------------|--------------------|-------------------|------------------|------------------|----------------|
| ✓ Steering Box/Rack | ✓ Steering linkage | ✓ Shock Absorbers | ✓ Bushes/Pivots | ✓ Tyre Wear | ✓ Wheel/ Spare |
| ✓ Oil Leaks | ✓ Power Steering | ✓ Springs | ✓ Wheel Bearings | ✓ Tyre Condition | ✓ Driveability |

Comments:

Brakes

- | | | | | | |
|---------------|------------------|-------------------|---------------------|---------------------|---------------|
| ✓ Operation | - Pads/lining | ✓ Pedal Height | ✓ Wiring | ✓ Indicators | ✓ Battery |
| ✓ Park brake | ✓ Line Condition | ✓ Pedal Rubbers | ✓ Headlights/Aim | ✓ Instrumentation | ✓ Charge Rate |
| ✓ Fluid leaks | ✓ Hose Condition | - ABS check light | A Exterior Lighting | ✓ Windscreen Wipers | ✓ Horn |

Comments:

VARIOUS LIGHTS NEEDS ATTENTION

Body

- | | | | | | |
|-------------|-------------------|--------------------|-------------------|------------------|----------------|
| ✓ Structure | A Panel condition | ✓ Previous Repairs | ✓ Door/Window op | ✓ Door Locks | ✓ Seat Belts |
| A Corrosion | A Paint Condition | ✓ Windscreen/glass | ✓ Windows Tinting | A Seats and Trim | ✓ Door handles |

Comments:

ORIGINAL SEATS SHOW WEAR OTHERWISE CLEAN AND TIDY

MINOR PANEL AND PAINT DEFECTS. VARIOUS UNDERSIDE SURFACE RUST

Miscellaneous

- | | | | | | |
|------------|-------------------|----------|------------------|---------------------------------------|---------|
| ✓ Demister | ✓ Air conditioner | ✓ Heater | - LPG Compliance | - Ability to run on Alternative Fuels | A Other |
|------------|-------------------|----------|------------------|---------------------------------------|---------|

Comments:

INTERIOR CLOCK INOPERATIVE

STARTER MOTOR HESITATES AND UNRELIABLE

ACCREDITED PREPURCHASE INPECTION REPORT TERMS AND CONDITIONS

Pre-purchase inspection reports are based on a visual inspection of the condition of the specific items set out in this report form.

Neither Shannons nor Sangate service company Pty Ltd will be responsible for any defects that could reasonably be expected to have become evident by the dismantling or removal of parts of the vehicle or by inspection of any items not set out in the report form.

Supplementary restraint or air bag systems have been specifically excluded from this test due to the complexity of test procedures. Customers who are considering the purchase of a vehicle fitted with an srs or air bag system are advised to refer the vehicle to an authorized service agent for system functionality.

The pre – purchase inspection report is not substitute for a roadworthy test, which is a tolerance test. The customer acknowledges that receipt of a satisfactory condition report does not mean the vehicle will also pass a roadworthy test.

Sangate will not be held liable for

- a) Carrying out pre-purchase or any services connected with such inspections: or
- b) Providing to any person any information in connection with a pre-purchase vehicle inspection including this report form.

To the extent permissible under the Trade Practices Act and any other act of Parliament, the liability of Sangate for any loss or damage to the vehicle for:

- a) Any breach of any term, condition or warranty implied by such legislation shall be limited to the supply of the service and shall be equivalent to the cost of having the service supplied; and
- b) Any breach of contract or statute or any tort by Sangate shall be limited to an amount equal to the pre- purchase inspection fee paid.