

ID	Vehicle	Service Description	Shop	Service Date	Mileage
71	1979 Rolls-Royce Silver W	Hankook Tires Installed at Central Tire, Verona, VA	Central Tire, Veron	6/18/2013	23,558
70	1979 Rolls-Royce Silver W	Purchased 5 Hankook Optimo H724 P235-75R15 108S	Brian Vogel	6/13/2013	23,557
69	1979 Rolls-Royce Silver W	Replace front Compliance Mounts (UR72000 - \$101.50 for 2 from Robe	GK Automotive, Ve	6/13/2013	23,557
72	1979 Rolls-Royce Silver W	Front Wheel Alignment (after compliance mounts replaced)	GK Automotive, Ve	6/13/2013	
68	1979 Rolls-Royce Silver W	Replace rusted exhaust pipes	GK Automotive, Ve	5/30/2013	23,557
66	1979 Rolls-Royce Silver W	Road test car to assess braking & engine - both seem fine	Brian Vogel	5/29/2013	23,537
64	1979 Rolls-Royce Silver W	Flush brake & height control system; refill with YAK363 & bleed system	Brian Vogel	5/28/2013	23,537
67	1979 Rolls-Royce Silver W	Reset fast idle and regular idle speeds; check timing	Brian Vogel	5/24/2013	23,537
65	1979 Rolls-Royce Silver W	Remove anti-dieseling & weakener solenoids; clean electrical connectio	Brian Vogel	5/22/2013	23,537
63	1979 Rolls-Royce Silver W	Install new NGK BPR4EY Spark Plugs gapped to 0.035"	Brian Vogel	4/30/2013	23,537
61	1979 Rolls-Royce Silver W	Refill cooling system with 2-EHA-free extended life antifreeze (OEM Bra	Brian Vogel	2/12/2013	23,537
62	1979 Rolls-Royce Silver W	Install Derale 17118 fan clutch fan & Hayden 2706 viscous fan clutch	Brian Vogel	2/10/2013	23,537
60	1979 Rolls-Royce Silver W	Remove Radiator & have damage from fan self-destruct repaired at Do	Brian Vogel	1/15/2013	23,537
54	1979 Rolls-Royce Silver W	Install PTFE core high pressure accumulator to body hose on System 1	Brian Vogel	10/11/2012	23,537
52	1979 Rolls-Royce Silver W	Rebuild System 1 (right side) accumulator control valve	Brian Vogel	10/11/2012	23,537
53	1979 Rolls-Royce Silver W	Recharge System 1 (right side) accumulator	Brian Vogel	10/11/2012	23,537
59	1979 Rolls-Royce Silver W	Repaired door light switch on passenger side front door	Brian Vogel	3/20/2012	23,537
58	1979 Rolls-Royce Silver W	Top-Up SU Carb Dash Pots with Dexron ATF	Brian Vogel	3/16/2012	23,537
56	1979 Rolls-Royce Silver W	Replace gravity feed hoses from brake/hydraulic reservoir to pumps. U	Brian Vogel	3/15/2012	23,537
55	1979 Rolls-Royce Silver W	Replace reservoir filters with custom made version that does not collap	Brian Vogel	3/15/2012	23,537
57	1979 Rolls-Royce Silver W	Replace return hoses from accumulators to reservoir. ¼" ID	Brian Vogel	3/15/2012	23,537
39	1979 Rolls-Royce Silver W	Correct short in bonnet/hood light	Brian Vogel	2/1/2012	23,537
34	1979 Rolls-Royce Silver W	Refill HP Gear Oil in Trunnion/Detroit Joints	Brian Vogel	2/1/2012	23,537
36	1979 Rolls-Royce Silver W	Drain & Refill Coolant - Used SuperTech Extended Life	Brian Vogel	2/1/2012	23,537
37	1979 Rolls-Royce Silver W	Oil Change - SuperTech 10W40 (regular oil)	Brian Vogel	2/1/2012	23,537
38	1979 Rolls-Royce Silver W	Fix Splice for ammeter shunt. Covered splice with 3M Temflex rubber s	Brian Vogel	2/1/2012	23,537
35	1979 Rolls-Royce Silver W	Drain & Refill Final Drive/Differential with 75W140 Synthetic HP Gear O	Brian Vogel	2/1/2012	23,537
32	1979 Rolls-Royce Silver W	Replace wheel cap center medallion	Darbyshires Classic	6/9/2006	
33	1979 Rolls-Royce Silver W	Replace fuel tank sending unit	Darbyshires Classic	6/9/2006	
27	1979 Rolls-Royce Silver W	Replaced Power Steering Rack	Bentley High Point	11/22/2004	23,061
26	1979 Rolls-Royce Silver W	Replace main & carb fuel filters	Bentley High Point	11/22/2004	23,061
25	1979 Rolls-Royce Silver W	Adjust Floats	Bentley High Point	11/22/2004	23,061
23	1979 Rolls-Royce Silver W	Replace Fuel Bowl Covers	Bentley High Point	11/22/2004	23,061
28	1979 Rolls-Royce Silver W	R&R and Overhauled G-Valve	Bentley High Point	11/22/2004	23,061
20	1979 Rolls-Royce Silver W	Overhaul Brake Pressure Sensors	Bentley High Point	11/22/2004	23,061
24	1979 Rolls-Royce Silver W	Replace Needle Valves & Seats	Bentley High Point	11/22/2004	23,061
19	1979 Rolls-Royce Silver W	Replace System 2 high pressure hose from pump to accumulator	Bentley High Point	11/22/2004	23,061

Cost	🕒
\$104.44	🕒(0)
\$503.13	🕒(0)
\$271.00	🕒(0)
\$0.00	🕒(0)
\$356.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$17.06	🕒(0)
\$22.50	🕒(0)
\$75.00	🕒(0)
\$42.50	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$580.95	🕒(0)
\$2,773.26	🕒(0)
\$649.89	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)
\$67.79	🕒(0)
\$4,202.38	🕒(0)
\$0.00	🕒(0)
\$0.00	🕒(0)

ID	Vehicle	Service Description	Shop	Service Date	Mileage
18	1979 Rolls-Royce Silver W	Overhaul brake/hydraulic reservoir - replace baffles & seals	Bentley High Point	11/22/2004	23,061
17	1979 Rolls-Royce Silver W	Overhaul front brake calipers & replace pads	Bentley High Point	11/22/2004	23,061
16	1979 Rolls-Royce Silver W	Replace front and subframe hydraulic hoses	Bentley High Point	11/22/2004	23,061
15	1979 Rolls-Royce Silver W	Overhaul Accumulators & Valves	Bentley High Point	11/22/2004	23,061
14	1979 Rolls-Royce Silver W	Check Brakes	Bentley High Point	11/22/2004	23,061
21	1979 Rolls-Royce Silver W	Repair Fuel Leak	Bentley High Point	11/22/2004	23,061
30	1979 Rolls-Royce Silver W	Replace Gear Selector Pointer (UR20001)	Bentley High Point	11/22/2004	23,061
31	1979 Rolls-Royce Silver W	Repair Speedometer	Bentley High Point	11/22/2004	23,061
22	1979 Rolls-Royce Silver W	R&R and Overhauled Carburetors	Bentley High Point	11/22/2004	23,061
29	1979 Rolls-Royce Silver W	Front End Alignment	Bentley High Point	11/22/2004	23,061
13	1979 Rolls-Royce Silver W	Ammeter Shunt (UD18802) [no record of part or installation costs]	Transco (now Bent	6/2/1998	
12	1979 Rolls-Royce Silver W	Replacement distribution valve (UR15984) - Part Cost Only	Transco (now Bent	6/27/1995	
11	1979 Rolls-Royce Silver W	Front & Rear Brake Pads (no record of installation)	EuroMotorcars	4/7/1995	
40	1979 Rolls-Royce Silver W	Replace Thermostat & Gasket	Transco (now Bent	11/8/1990	17,024
41	1979 Rolls-Royce Silver W	Replaced Scuttle Filter	Transco (now Bent	11/8/1990	17,024
6	1979 Rolls-Royce Silver W	Bleed Brake System	Transco (now Bent	7/20/1984	
9	1979 Rolls-Royce Silver W	Repair rattle in RHF door - loose window motor bolt	Transco (now Bent	7/20/1984	
5	1979 Rolls-Royce Silver W	6K Service, Lube & Oil Filter	Transco (now Bent	7/20/1984	
8	1979 Rolls-Royce Silver W	Replace carb needles & seats, cleaned carbs & pipes, replaced carb fuel	Transco (now Bent	7/20/1984	
4	1979 Rolls-Royce Silver W	Seats not operating - blown wiper fuse related	Transco (now Bent	7/20/1984	
3	1979 Rolls-Royce Silver W	High Beam Lamp taped back in place	Transco (now Bent	7/20/1984	
2	1979 Rolls-Royce Silver W	Replace wiper motor & drive cable	Transco (now Bent	7/20/1984	
10	1979 Rolls-Royce Silver W	Parts related to above repairs/service	Transco (now Bent	7/20/1984	
7	1979 Rolls-Royce Silver W	Replace upper radiator hose/change antifreeze	Transco (now Bent	7/20/1984	
42	1979 Rolls-Royce Silver W	Repair New Speedometer - Clicks at Low Speed (Replaced Speedomete	Transco (now Bent	6/16/1982	3,208
1	1979 Rolls-Royce Silver W	Replace defective speedometer/odometer (UD22129)	Transco (now Bent	3/17/1982	3,139
43	1979 Rolls-Royce Silver W	Change Oil & Filter	Transco (now Bent	2/19/1982	2,888
44	1979 Rolls-Royce Silver W	Replaced Brake Hoses & Installed Heat Shield (Warranty Repair)	Transco (now Bent	8/27/1981	2,543
47	1979 Rolls-Royce Silver W	Replaced bolts in LF window motor mounting	Transco (now Bent	8/27/1981	2,543
48	1979 Rolls-Royce Silver W	Adjusted Boot/Trunk Lid	Transco (now Bent	8/27/1981	2,543
49	1979 Rolls-Royce Silver W	Change Oil & Filter; Lube Chassis	Transco (now Bent	8/27/1981	2,543
50	1979 Rolls-Royce Silver W	Replace power steering and AC belts	Transco (now Bent	8/27/1981	2,543
46	1979 Rolls-Royce Silver W	Adjust left front door seal - hits body	Transco (now Bent	8/27/1981	2,543
51	1979 Rolls-Royce Silver W	Replace final drive/differential pinion seal	Transco (now Bent	8/27/1981	2,543
45	1979 Rolls-Royce Silver W	Replaced Speed Control Switch and Gear Change Scale	Transco (now Bent	8/27/1981	2,543
Total					

Cost	₹
\$0.00	₹(0)
\$0.00	₹(0)
\$0.00	₹(0)
\$0.00	₹(0)
\$0.00	₹(0)
\$0.00	₹(0)
\$70.63	₹(0)
\$281.70	₹(0)
\$0.00	₹(0)
\$89.95	₹(0)
\$0.00	₹(0)
\$307.77	₹(0)
\$287.24	₹(0)
\$0.00	₹(0)
\$0.00	₹(0)
\$0.00	₹(0)
\$19.00	₹(0)
\$57.00	₹(0)
\$114.00	₹(0)
\$0.00	₹(0)
\$0.00	₹(0)
\$57.00	₹(0)
\$433.28	₹(0)
\$19.00	₹(0)
\$0.00	₹(0)
\$0.00	₹(0)
\$100.65	₹(0)
\$0.00	₹(0)
\$0.00	₹(0)
\$0.00	₹(0)
\$0.00	₹(0)
\$0.00	₹(0)
\$0.00	₹(0)
\$360.38	₹(0)
\$123.50	₹(0)
\$11,987.00	