



I Con indicatore visivo di usura

2 fori: OK
1 foro: VERIFICARE
0 fori: SOSTITUIRE!

UK With visual indicator of use

2 marks: OK
1 mark: CHECK
0 marks: REPLACE!

D Mit Verschleißanzeige

2 Bohrungen: OK
1 Bohrung sichtbar: KONTROLLIEREN
0 Bohrungen sichtbar: SOFORT AUSTAUSCHEN!

F Avec témoin visuel d'usure

2 témoins: OK
1 témoin: VÉRIFIEZ
0 témoins: REMPLACEZ!

E Con indicador de desgaste

2 muescas: OK
1 muesca: COMPROBAR
0 muescas: ¡SUSTITUIR!

DK Med visuel slidindikator

2 huller: OK
1 hul: KONTROLLÉR
0 huller: UDSKIFT!

